



GREG BELL Lieutenant Governor

# State of Utah

#### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

#### Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representativ	Representatives Present During the Inspection:				
Company	Dennis Oakley				
OGM	Karl Houskeeper				

# **Inspection Report**

Permit Number:	C0150018		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, January 06, 2011		
Start Date/Time:	1/6/2011 9:00:00 AM		
End Date/Time:	1/6/2011 1:00:00 PM		
Last Inspection:	Tuesday, December 14, 2010		

Inspector: <u>Karl Houskeeper,</u>
Weather: <u>Clear, Temp. 20 Deg. F.</u>
InspectionID Report Number: <u>2611</u>

of Operations

Accepted by: jhelfric 1/26/2011

Permitee: **ENERGY WEST MINING CO**Operator: **ENERGY WEST MINING CO** 

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

19,740.78	Total Permitted
98.05	Total Disturbed
0.60	Phase I
	Phase II
	Phase III

Mineral	Ownership	Types
---------	-----------	-------

✓ Federal
✓ Underground
✓ State
✓ Surface
✓ County
✓ Fee
✓ Processing
✓ Other
✓ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Salk Dousbuga

Date

Thursday, Janua



Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Thursday, January 06, 2011

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	<b>V</b>		<b>Y</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
<u> </u>	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓		✓	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	Roads: Construction, Maintenance, Surfacing				
16.Ł	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other	<b>✓</b>		<b>V</b>	

Permit Number: C0150018 Inspection Type: PARTIAL

Inspection Date: Thursday, January 06, 2011

Page 3 of 3

## 2. Signs and Markers

The mine identification signs were observed at the Waste Rock facility, Mine Site and the Rilda Facility. All signs are located at the point of public access to the permit area and contain the required information.

#### 8. Noncoal Waste

A few items of noncoal waste were in the parking lot and around the shop area. The amount observed was minimal and showed a marked improvement from the previous inspection.

## 22. Other

Snow removal from the Rilda Facilities was taking place during the inspection The snow is being hauled to the Waste Rock Site.